



CRD TO MORANBAH PIPELINE



Plate C14: Area of Denison Creek Bed Designated and Photographed as Location G by SunWater



CRD TO MORANBAH PIPELINE



Plate C15: General View of Funnell Creek South of Junction with Boothill Creek to South of Junction with Denison Creek



CRD TO MORANBAH PIPELINE




Plate C16: General View of Funnel Creek South of Junction with Denison Creek



CRD TO MORANBAH PIPELINE




Plate C17: Funnel Creek Channel South of Northern End of Braided Section



CRD TO MORANBAH PIPELINE



Plate C18: Area of Funnel Creek Bed Designated and Photographed as Location C by SunWater



CRD TO MORANBAH PIPELINE




Plate C19: Funnel Creek Below Junction with Denison Creek



CRD TO MORANBAH PIPELINE



Plate C20: Funnel Creek South of Junction with Denison Creek Visited During Field Inspection



CRD TO MORANBAH PIPELINE



Plate C21: Area of Funnel Creek Bed at Eastern PowerLink Easement Designated and Photographed as Location E by SunWater



CRD TO MORANBAH PIPELINE



Plate C22: General View of Boothill Creek



CRD TO MORANBAH PIPELINE



Plate C23: Boothill Creek at Rosedale Road



CRD TO MORANBAH PIPELINE



Plate C24: Boothill Creek Upstream of Marlborough Sarina Road



CRD TO MORANBAH PIPELINE




Plate C25: Boothill Creek Below Marlborough Sarina Road



CRD TO MORANBAH PIPELINE




Plate C26: Boothill Creek Downstream of Marlborough Sarina Road



CRD TO MORANBAH PIPELINE




Plate C27: Boothill Creek at Windmill



CRD TO MORANBAH PIPELINE




Plate C28: General View of The Junction and Funnel Creek Below The Junction



CRD TO MORANBAH PIPELINE



Plate C29: The Junction Visited During Field Inspection



CRD TO MORANBAH PIPELINE



Plate C29: General View of Connors River at Mount Bridget Bend and Junction with Sandy Creek



CRD TO MORANBAH PIPELINE




Plate C30: Area of Connors River Bed at Junction with Sandy Creek Designated and Photographed as Location B by SunWater



CRD TO MORANBAH PIPELINE



Plate C31: Connors River at Mount Bridget Bend



Table C1: Surface Areas of Observed Sand Resource Extents

Location	Surface Area (m²)	
<u>North Creek</u> Section of North Creek bed south of Peak Downs Highway and west of Daunia Road		59 234
<u>Harrybrandt Creek</u> Section of Harrybrandt Creek bed south of Peak Downs Highway adjacent to Coppabella Mine	234 748	410 093
Section of Harrybrandt Creek bed south of Peak Downs Highway east of Coppabella Mine	133 040	
Section of Harrybrandt Creek bed east of northern end of Fitzroy Development Road	42 306	
<u>Bee Creek</u> Section of Bee Creek bed adjacent to BMA Easement	18 743	133 177
Section of Bee Creek bed south of BMA Easement at northern end of braided section	14 041	
Section of Bee Creek eastern channel bed south of BMA Easement	100 394	
<u>Possible filled old Nebo Creek channel</u> Possible filled old Nebo Creek channel between Peak Downs Highway and BMA Easement		997 112
<u>BMA Pit</u> Worked section of BMA Pit		11 420
Possible filled old Nebo Creek channel northern extension to worked section of BMA Pit	22 740	103 780
Possible filled old Nebo Creek channel southern extension to worked section of BMA Pit	81 040	
<u>Denison Creek</u> Section of Denison Creek bed designated and photographed as Location G by SunWater	5 514	62 050
Section of Denison Creek bed east of Braeside Bore Field		



CRD TO MORANBAH PIPELINE

Table C1: Surface Areas of Observed Sand Resource Extents (Continued)

Location	Surface Area (m ²)			
<u>Funnel Creek</u> Section of Funnel Creek bed designated and photographed as Location C by SunWater	6 470		407 094	
Section of Funnel Creek channel bed south of northern end of braided section		173 426		
Section of Funnel Creek bed south of junction with Denison Creek visited during field inspection	2 218			
Section of Funnel Creek bed below junction with Denison Creek		51 185		
Section of Funnel Creek bed at eastern PowerLink Easement designated and photographed as Location E by SunWater		182 483		
<u>Boothill Creek</u> Section of Boothill Creek bed at Rosedale Road		30 072	259 254	
Section of Boothill Creek bed upstream of Marlborough Sarina Road		105 003		
Section of Boothill Creek bed below Marlborough Sarina Road visited during field inspection	5 101			
Section of Boothill Creek bed below Marlborough Sarina Road		24 918		
Section of Boothill Creek bed downstream Marlborough Sarina Road		50 644		
Section of Boothill Creek bed at Windmill visited during field inspection	17 371			
Section of upstream extension of Boothill Creek bed at Windmill	6 585			
Section of downstream extension of Boothill Creek bed at Windmill	24 661	48 617		
<u>The Junction</u> Section of The Junction bed visited during field inspection	14 518			59 343
Section of The Junction bed				
<u>Connors River</u> Section of Connors River bed at Sandy Creek junction designated and photographed as Location B by SunWater	39 797		282 310	
Section of Connors River bed at Mount Bridget point bar	242 513			



APPENDIX D

Limitations

LIMITATIONS

This Document has been provided by Golder Associates Pty Ltd ("Golder") subject to the following limitations:

This Document has been prepared for the particular purpose outlined in Golder's proposal and no responsibility is accepted for the use of this Document, in whole or in part, in other contexts or for any other purpose.

The scope and the period of Golder's Services are as described in Golder's proposal, and are subject to restrictions and limitations. Golder did not perform a complete assessment of all possible conditions or circumstances that may exist at the site referenced in the Document. If a service is not expressly indicated, do not assume it has been provided. If a matter is not addressed, do not assume that any determination has been made by Golder in regards to it.

Conditions may exist which were not detected given the limited nature of the enquiry Golder was retained to undertake with respect to the site. Variations in conditions may occur between assessment locations, and there may be special conditions pertaining to the site which have not been revealed by the investigation and which have not therefore been taken into account in the Document. Accordingly, additional studies and actions may be required.

In addition, it is recognised that the passage of time affects the information and assessment provided in this Document. Golder's opinions are based upon information that existed at the time the information is collected. It is understood that the Services provided allowed Golder to form no more than an opinion of the actual conditions of the site at the time the site was visited and cannot be used to assess the effect of any subsequent changes in the quality of the site, or its surroundings, or any laws or regulations.

Any assessments, designs, and advice provided in this Document are based on the conditions indicated from published sources and the investigation described. No warranty is included, either express or implied, that the actual conditions will conform exactly to the assessments contained in this Document.

Where data supplied by the client or other external sources, including previous site investigation data, have been used, it has been assumed that the information is correct unless otherwise stated. No responsibility is accepted by Golder for incomplete or inaccurate data supplied by others.

Golder may have retained subconsultants affiliated with Golder to provide Services for the benefit of Golder. To the maximum extent allowed by law, the Client acknowledges and agrees it will not have any direct legal recourse to, and waives any claim, demand, or cause of action against, Golder's affiliated companies, and their employees, officers and directors.

This Document is provided for sole use by the Client and is confidential to it and its professional advisers. No responsibility whatsoever for the contents of this Document will be accepted to any person other than the Client. Any use which a third party makes of this Document, or any reliance on or decisions to be made based on it, is the responsibility of such third parties. Golder accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this Document.

At Golder Associates we strive to be the most respected global group of companies specialising in ground engineering and environmental services. Employee owned since our formation in 1960, we have created a unique culture with pride in ownership, resulting in long-term organisational stability. Golder professionals take the time to build an understanding of client needs and of the specific environments in which they operate. We continue to expand our technical capabilities and have experienced steady growth with employees now operating from offices located throughout Africa, Asia, Australasia, Europe, North America and South America.

Africa	+ 27 11 254 4800
Asia	+ 852 2562 3658
Australasia	+ 61 3 8862 3500
Europe	+ 356 21 42 30 20
North America	+ 1 800 275 3281
South America	+ 55 21 3095 9500

solutions@golder.com
www.golder.com



Golder Associates Pty Ltd
611 Coronation Drive
Toowong Queensland 4066
Australia
T: +61 7 3721 5400

